

#### ADDENDUM

#### **ADDENDUM NO.:** #01 **DATE:** 08/29/2024

**PROJECT:** NDOT 1600 Renovation **PROJECT #:** 23053

**TO:** Prospective Bidders

This Addendum is issued by the Architect to all bidders of record prior to receipt of proposals. Bidders shall acknowledge receipt of this addendum by so indicating on the Proposal Form. Failure to do so may subject Bidder to disqualification. All information and instructions given herein shall become a part of the Contract Documents.

#### **GENERAL**

- 1. Questions due by September 10th at 5:00 pm.
- 2. New Bid Date: September 19th at 3:00 pm.
- 3. Addendum 02 to be released September 12th
- 4. Prebid Meeting agenda attached
- 5. Prebid sign in sheet attached
- 6. Hazardous Report attached

#### PROJECT MANUAL

- 1. Section 00 10 00 Notice to Bidders
  - a. New Bid Date: September 19th at 3:00 pm.
  - b. Revise the following "...submitted in a sealed envelope marked "**Ogallala Rest Area Bid**". to "... submitted in a sealed envelope marked "**NDOT 1600 Office Renovation**".
  - c. Bids mailed to the office shall be addressed to:

Madison Sherwood Nebraska Dept. of Transportation Operations Division - attn: CAP FAC PO Box 94759 Lincoln, NE 68509-4759

d. Bids delivered in person shall be delivered to:

Madison Sherwood Nebraska Dept. of Transportation Operations Division - attn: CAP FAC 5001 South 14th Street Lincoln. NF 68512

- 2. Section 00 20 00 Instructions to Bidders
  - a. 8.02 Liquidated Damages , Section B



i. Amount of liquidated damages shall be \$500.00 per day for each and every calendar day the work remains unfinished after the established date of substantial completion which is 480 calendar days following the issuance of the Notice to Proceed.

#### END OF ADDENDUM



## PRE-BID CONFERENCE

Good Life. Great Journey.

**DEPARTMENT OF TRANSPORTATION** 

District 0 NDOT Building 1600 Renovation PROJECT AFE K-002 Wednesday, August 28, 2024 10:00AM Local Time

### INTRODUCTORY REMARKS:

INTRODUCE SELF – GOOD Morning! I am Jeff Jensen – Facilities Construction Coordinator II for the Nebraska Department of Transportation. I would like to THANK YOU for your interest in the above mentioned project.

The Purpose of this conference is to answer any Administrative or Technical questions you may have and to provide you with an opportunity to look at the Project Site.

INTRODUCTIONS - I would like to make some Introductions:

Joshua Cowan, NDOT - Facilities Engineering Manager

Mark Hamilton, NDOT – Maintenance Manger II Wes Nelson, NDOT – Maintenance Manager I Matt Smith, BVH Architecture – Architect Amanda Schnatz, BVH Architecture – Architect Alicea Ringer, BVH Architecture – Project Coordinator David Carey – Olssons – Electrical Engineer John Meyers, Olssons – Mechanical Engineer

SIGN IN SHEET– Has everyone had a chance to sign the Sign In Sheets that are circulating? Be sure and sign in before you leave.

#### ADDENDUMS

Be sure to check at the officially designated plan room service for any addendums prior to bidding.

#### **BID FORM**

On completing the Bid Proposal Form contained in the Bid Packet (Section 00 40 00):

- 1. Please fill out the Bid form completely for all applicable items.
- 2. Sign the Bid Form in <u>Blue Ink</u>.
  - Bids received without original signature or
  - signed in pencil will not be accepted.
- 3. Return all pages of the Bid Form.
- 4. On the Bid Form, there is a Total Base Bid Amount.
- 5. Be sure to enter your Bid Proposal amounts correctly in both words and figures as required on the Bid Proposal Form.
- 6. The Bid Review Committee will review the Bids for any discrepancies.
- 7. Provide the bid in an envelope marked "BID".

### **BID** NDOT District O 1600 Building Renovation

#### **BIDS DUE**

1. The Bids are due NO LATER THAN 3:00:00 PM on Thursday, September 12<sup>th</sup>, 2024

Bids mailed to this office shall be addressed to: Madison Sherwood

Nebraska Dept. of Transportation Operations Division-attn: CAP FAC PO Box 94759 Lincoln, NE 68509-4759

Bids delivered in person shall be delivered to: Madison Sherwood

 Madison Sherwood Nebraska Dept. of Transportation Operations Division-attn: CAP FAC 5001 South 14<sup>th</sup> Street Lincoln, NE 68512

- 2. Parking is available in the South Parking Lot.
- 3. The Bids will be publicly <u>opened</u> and <u>recorded</u>. You are welcome to stay and attend the Bid Opening.

#### DRUG POLICY

By signing the Bid Proposal, the Bidder is committed to provide a drug free workplace environment. If requested by the Nebraska Department of Transportation, the Bidder must furnish evidence that they have a Drug Free Workplace Policy.

#### BID REVIEW COMMITTEE

The "Bid Review Committee" will meet within one week after the Public Bid Opening to review the bids for any irregularities and to award the contract on the Project.

#### CONTRACT REVIEW

Contracts will then be prepared by CAP FAC and reviewed by a representative of the Nebraska Attorney General. The contract review takes about two weeks. Once the contract review is complete, the contracts will go to the Contractor for signature.

#### LIQUIDATED DAMAGES

Liquidated damages will be assessed for this project in the amount of \$500/day for every calendar day the work remains unfinished after the established date of substantial completion which is 480 calendar days following the issuance of the Notice to Proceed.

#### MANDATORY MEETINGS

After the Contract is fully executed, a PRE-CONSTRUCTION MEETING will be held at a Nebraska Department of Transportation facility near the project location after the Contracts, Performance Bonds, and Certificate of Insurance have been received.

#### **INVOICE PAYMENTS ON PROJECT**

1. Payments will be made by DIRECT DEPOSIT on the project in accordance with State of Nebraska procedures. Payments will be made within 45 days after the invoices are received at the CAP FAC Office.

- 2. The Nebraska State Treasurer requires that payments in excess of \$25,000 will be made by direct deposit instead of State Warrants (checks).
- 3. The Contractor must establish a direct deposit payments enrollment with the State Treasurer (ACH Automated Clearing House). The enrollment form will be provided at the Pre-Construction Meeting.

#### EQUIPMENT STORAGE & MATERIAL STORAGE AT THE SITE

The <u>Contractor is responsible</u> for the security of their equipment and any materials left at the site.

The Contractor is expected to keep the construction site clean and free of trash and debris during the project. <u>Daily</u> cleaning shall be completed.

#### USE OF SITE

The <u>Contractor is responsible</u> for the security and safety of the site at all times.

The construction area should be kept neat and tidy, and adjacent space and roads to be kept clean and clear. Contractor responsible for repair of any damages to facilities and property on a <u>Daily</u> basis.

#### HOURS OF OPERATION AT THE PROJECT LOCATION:

The Contractor will have control of the project site and building hours are 8:00am - 4:30 PM, but they can access the building early or late with provided security badges. Please notify NDOT site contact if work will be performed on holidays or a weekend.

#### COORDINATION ON OTHER CONSTRUCTION AT FACILITY

Asbestos Abatement will proceed the start of this project, so minor coordination may be required.

#### USE OF SANITARY FACILITIES:

Supply and upkeep of appropriate Sanitary Facilities will be the responsibility of the Contractor for Contractor staff and sub-contractors working at the site.

Contractor is asked to not use existing facilities on-site and instead should provide temporary facilities for project.

This project is a high visibility project, and communication is critical to this project.

#### ALTERNATIVE/ADDITIVE BID ITEMS

There are no Alternate Bids Items and no Unit Price Item called out for in this project.

#### **CONSULTANT COMMENTS**

#### CONTRACTOR QUESTIONS AND COMMENTS

#### MEETING ADJOURNED TO PROJECT SITE FOR ADDITIONAL QUESTIONS:

PROJECT SITE EXAMINATION

|          | NEBRASKA<br>Good Life. Great Journey.<br>Department of transportation |                                 | NDOT           | SIGN-IN SHEET<br>NDOT DISTRICT 0 1600 Building Renovation<br>AFE K-002<br>August 28, 2024<br>10:00AM local Time |
|----------|---|---------------------------------|----------------|---|
|          | Name:   | Company/Firm/Agency:            | Phone Number:  | E-Mail Address:   |
| <i>.</i> | Joshua Cowan  | NDOT – Operations CAP FAC       | 402.479.3746   | joshua.cowan@nebraska.gov   |
| 5.       | Jeff Jensen   | NDOT – Operations CAP FAC       | 531.207.5002   | jeff.jensen@nebraska.gov  |
| С        | Mark Hamilton   | NDOT – District 0 - Maintenance | 402.479.4882   | mark.hamilton@nebraska.gov  |
| 4.       | Wes Nelson WWN  | NDOT – District 0 – Maintenance | 402.479.3995   | wes.nelson@nebraska.gov   |
| 5.       | Matt Smith  | BVH Architecture                | 402.905.9748   | msmith@bvh.com  |
| 6.       | Amanda Schnatz  | BVH Architecture                | 402.889.5212   | aschnatz@bvh.com  |
| 7.       | Alicea Ringer   | BVH Architecture                | 402.345.3060   | aringer@bvh.com   |
| ö        | David Carey   | Olssons                         | 402.730.8240   | dcarey2@olssons.com   |
| 6.       | John Meyers   | Olssons                         | 402.540.7023   | jmeyers@olssons.com   |
| 10.      | Mixe chulug   | weit 2                          | U02. 982. 3027 | Mike ghaly a weitz. Com   |
|          | NDOT District 0 1600 Building Renovation                              | vation                          |                | PRE-BID MEETING<br>Page - 1   |

| Name:   | Company/Firm/Agency:       | Phone Number:  | E-Mail Address:                         |
|---|----------------------------|----------------|---|
| 11. Ray Brown   | Brown Righting             | 402/432-0868   | Ray & browhothers ]. com                |
| 12. JEREMY Jush                                       | berrounters Construction   |                | EST 2 MATINU @ 5000 700 - 6000 700 6725 |
| 13. Spencer Mequire                                   | Chrever Construction       | 462 - 367-8757 | smaguire @ cheever construction.com.    |
| 14. Bra Wehrs   | Kingary Const.             | 8052-048 ZOH   | 402 840-2508 brinn of 1400 brilds, COM  |
| 15. Broch Wyman                                       | D.R. Anderson Constructors |                | 402-637-6041 Buyman @ dranderson, com   |
| 16.   |                            |                |   |
| 17  |                            |                |   |
| 18.   |                            |                |   |
| 19.   |                            |                |   |
| 20.   |                            |                |   |
| 21.   |                            |                |   |
| NDOT District 0 1600 Building Renovation<br>AFE K-002 | lovation                   |                | PRE-BID MEETING<br>Page - 2             |

•

### BOCKMANN INC. 1420 CENTERPARK ROAD LINCOLN, NE. 68512



## LIMITED ASBESTOS SURVEY

## NDOT – 1600 Building

## 1600 Nebraska Parkway

LINCOLN, NEBRASKA

## INDEX

| Inspector                  | p.3        |
|----------------------------|------------|
| Survey Review              | p.4        |
| Asbestos Materials         | p.5        |
| Non-Asbestos Materials     | p.7        |
| Drawings                   | Appendix A |
| Inspection Field Sheets    | Appendix B |
| Laboratory Analysis Sheets | Appendix C |
| Certificates               | Appendix D |

## **INSPECTOR**

NAME: Ron Thompson

#### ADDRESS: 1420 CENTERPARK ROAD LINCOLN, NE 68502

PHONE: (402)423-6631

DATE OF INSPECTION: February 19th, 2024

 EPA CERTIFICATE #
 2 8 8 I 0 5 4

STATE OF NE. CERTIFICATE # NE-MP784

#### **SURVEY REVIEW**

On the date of February 19<sup>th</sup>, 2024 Bockmann Inc. representative, Ron Thompson conducted a limited asbestos survey of commercial building located at 1600 Nebraska Parkway in Lincoln, Nebraska. The purpose of the survey was to identify all ACBM (asbestos containing building materials) within the building. The survey was limited to the interior of the building.

Sampling was done in accordance with State and Federal regulations, with a minimum of one and a maximum of seven samples taken of each homogeneous area. "Homogeneous area" means an area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in color and texture. An independent third-party laboratory using Polarized Light Microscopy did analysis of bulk samples. The following is a summary of the materials, which were sampled.

In Appendix B there are copies of the bulk sampling records. The sampling records give a detailed description of the samples taken and where they were taken. Appendix C contains copies of the laboratory bench sheets, which show what fibrous materials (asbestos and non-asbestos) were present in the sample. The samples were analyzed in a progressive manner, which means that if a sample from a homogeneous area was found to contain asbestos then subsequent samples of the same homogeneous area were not analyzed.

#### Limitations

It should be noted that while this inspection has been performed using the current standards applied in the professional environmental industry, it is not a certification that all ACBM's have been located. Unforeseen spaces may occur within a facility, which may not be immediately obvious to an inspector who is not completely familiar with the building and who has only a limited time at the facility. Asbestos has also been used in many ways and in many types of building materials, some of which may contain asbestos as a contaminant rather than an intentional component. The actual quantities of ACBM's in this report are estimates and should be verified prior to any abatement project that may be done in the future.

#### Laboratory procedures

Asbestos analysis is performed by using the bulk sample(s) collected during the asbestos survey. The material is mounted on slides and analyzed for asbestos content using Polarized Light Microscopy (PLM), asbestos is identified by refractive indices, physical characteristics, color, etc. The amount of asbestos within a material is a visual estimation by the analyst using a stereoscope. Any material that shows asbestos present in an amount greater than 1% is considered to be an asbestos containing material.

### Building Materials Which Contain (>1%) Asbestos Include:

#### Hard Packed Pipe Fitting Insulation (Samples 01-03,27,33,54 and 72)

*Location*: Fittings on misc. water and steam lines with fiberglass on the straight runs of the pipes – throughout the building
 *Quantity*: Approx. 520 units x \$45 = \$24,300.00

#### Hard Packed Pipe Fitting Insulation (Sample 22)

| Location: | Fittings on misc. | drain lines in basement             |             |
|-----------|-------------------|-------------------------------------|-------------|
| Quantity: | Approx. 15 units  | 5                                   |             |
| Note:     | This material ma  | ay be is located above hard plaster | ceilings on |
|           | floors 1-3 also.  | 15+15+15=45 X \$45= \$2025.00       |             |

#### Mag Pipe Insulation (Samples 04-06 and 53)

| Location: | Misc. steam lines on all levels of the building   |
|-----------|---|
| Quantity: | Approx. 1,150 linear feet x \$25.00 = \$28,750.00 |

#### Tank Insulation (Samples 24-26)

| Location: | Horizontal tank located on the S side of the mechanical room |
|-----------|--|
| Quantity: | Approx. 40 square feet \$2000.00                             |

#### Tan 12"x12" Floor Tile (Sample 32)

| Location: | Room B-10  |
|-----------|--|
| Quantity: | 500 square feet × \$3 = \$1500.00                      |
| Note:     | The mastic beneath this tile does not contain asbestos |

#### Black Wrap Insulation (Sample 49)

| Location: | Misc. fittings above hard ceilings throughout building                 |
|-----------|--|
| Quantity: | >100 units Est. 300 x \$45.00 = \$13,500.00                            |
| Note:     | This material is located above hard plaster ceilings with little or no |
|           | accessibility so accurate quantities could not be established.         |

#### Tan 9"x9" Floor Tile (Samples 50,51,55 and 59)

| Location: | Misc. rooms on 1 <sup>st</sup> floor (see drawing in Appendix A) |
|-----------|--|
| Quantity: | 5,100 square feet x \$3 = \$15,300.00                            |
| Note:     | The mastic beneath this tile does not contain asbestos           |

#### Sprayed on Acoustical Material (Sample 52)

| Location: | Above plywood on top of windows on 1 <sup>st</sup> floor        |  |
|-----------|---|--|
| Quantity: | <100 square feet \$7500.00                                      |  |
| Note:     | Material was left when ceilings were abated at a previous time. |  |

#### <u>Gray 9"x9" Floor Tile</u> (Sample 58)

| Location: | Misc. rooms on 1 <sup>st</sup> floor (see drawing in Appendix A) |
|-----------|--|
| Quantity: | 1,550 square feet x \$3 =\$4650.00                               |
| Note:     | The mastic beneath this tile does not contain asbestos           |

#### **Sprayed on Acoustical Material** (Samples 64-68)

| Location: | Ceiling in misc. rooms on 2 <sup>nd</sup> floor (see drawing in Appendix A) |
|-----------|---|
| Quantity: | 7,615 square feet x \$18 = \$137,070.00                                     |
| Note:     | Above suspended ceilings in a majority of the areas                         |

### Tan 9"x9" Floor Tile (Samples 69 and 70)

| Location: | Misc. rooms on 2 <sup>nd</sup> floor (see drawing in Appendix A) |
|-----------|--|
| Quantity: | 4,240 square feet x \$3 = \$12,720.00                            |
| Note:     | The mastic beneath this tile does not contain asbestos           |

#### Gray 9"x9" Floor Tile (Samples 71 and 76)

| Location: | Misc. rooms on 2 <sup>nd</sup> floor (see drawing in | n Appendix A)   |
|-----------|--|-----------------|
| Quantity: | 3,425 square feet x \$3 = 10,275.00                  |                 |
| Note:     | The mastic beneath this tile does not co             | ontain asbestos |

## Building materials, which were sampled, but did not contain asbestos (<1%) include:

#### Tan 12"x12" Floor Tile/Mastic (Sample 07)

Location: Men's rest room S of shop

Quantity: Approx. 150 square feet

#### 2'x4' Ceiling Tile (fissures) (Sample 08)

Location:Misc. rooms W side of basementQuantity:>1,000 square feet

#### Tan 12"x12" Floor Tile/Mastic (Sample 09)

Location:Hall west side of basementQuantity:Approx. 300 square feet

#### 2'x4' Ceiling Tile (small holes) (Samples 10,11)

Location:Misc. rooms in basementQuantity:>1,000 square feet

#### 2'x2' Ceiling Tile (recessed/rough) (Sample 12)

Location:Misc. rooms in basementQuantity:>1,000 square feet

#### 2'x4' Ceiling Tile (recessed/sq. pattern) (Sample 13)

| Location: | Misc. rooms in basement |
|-----------|-------------------------|
| Quantity: | >1,000 square feet      |

#### Drywall (Samples 14,23,74)

Location:Misc. walls and ceilings throughoutQuantity:>1,000 square feet

#### Sprayed on Acoustical Material (Samples 15-17)

Location:S side of two S-W rooms in basement (ceiling)Quantity:Approx. 200 square feet

#### 2'x2' Ceiling Tile (small sq. pattern) (Sample 18)

| Location: | Misc. rooms in basement |
|-----------|-------------------------|
| Quantity: | <200 square feet        |

#### Rough Plaster (sub-strate) (Samples 19,44-48)

Location: Misc. ceilings that have been abated at a previous timeQuantity: >1,000 square feet

#### Tan 12"x12" Floor Tile/Mastic (Sample 20)

Location:Central rest rooms in basementQuantity:>1,000 square feet

#### 2'x2' Ceiling Tile (small holes) (Samples 21,31)

Location: Central rest rooms in basementQuantity: >1,000 square feet

#### Off White Sheet Flooring (Sample 28)

Location:Store room B-6 in basementQuantity:20 square feet

#### 2'x4' Ceiling Tile (Sample 29)

Location:Misc. rooms in basementQuantity:<1,000 square feet</th>

#### Off White Sheet Flooring (Sample 30)

Location:East end of hall east side of basementQuantity:15 square feet

#### Smooth Coat Plaster (Samples 34-40)

Location:Misc. ceilings and walls throughoutQuantity:>10,000 square feet

#### 2'x2' Ceiling Tile (rough) (Samples 41-43)

Location:Misc. rooms 1st floorQuantity:>1,000 square feet

#### Off White 9"x9" Floor Tile/Mastic (Samples 56 and 73)

Location:Main halls on 1st and 2nd floorsQuantity:Approx. 2,350 square feet

#### Tar Paper (Sample 57)

Location:Main halls on 1st floor (beneath off white 9" floor tile)Quantity:Approx. 1,175 square feet

#### 2'x2' Ceiling Tile (recessed/smooth) (Sample 60)

| Location: | Misc. rooms on 1 <sup>st</sup> floor |
|-----------|--------------------------------------|
| Quantity: | >1,000 square feet                   |


#### 2'x2' Ceiling Tile (recessed/rough) (Samples 61-63)

Location:Misc. rooms on 2<sup>nd</sup> floorQuantity:>1,000 square feet

#### 2'x2' Ceiling Tile (recessed) (Sample 75)


| Location: | Misc. rooms on 3 <sup>rd</sup> floor |
|-----------|--------------------------------------|
| Quantity: | >1,000 square feet                   |

Appendix A




Basement

Sample locations and approx. locations




First Floor

Sample locations and approx. locations




Second Floor

Sample locations and approx. locations




Asbestos Floor Tile (mastic is non-asbestos)

Basement




Asbestos Floor Tile (mastic is non-asbestos)

First Floor



Asbestos Floor Tile (mastic is non-asbestos)

Second Floor



Asbestos Sprayed on Acoustical Ceilings

Second Floor

## Appendix B

Location:\_\_\_\_\_\_Lincoln, Nebraska\_\_\_\_\_

Inspector: Ron Thompson \_\_\_\_ Job #: \_\_\_\_2024-0059 \_\_\_\_ Cert #: \_NE-MP784 \_\_\_\_\_

| Sample<br>Number | Location   | Material Sampled                               | Homog. Area                          |
|------------------|--|--|--------------------------------------|
| 01               | S-E side of shop 45° fitting                         | Hard Packed Pipe Fitting<br>Insulation         | Misc. fittings<br>throughout         |
| 02               | N-E side of N-W room in basement<br>90° fitting 6"   | (positive stop                                 | Samples 01-03)                       |
| 03               | Middle N-W side of basement<br>90° fitting 3"        | d  | 2                                    |
| 04               | Hall W of mechanical room in<br>basement             | Mag Pipe Insulation                            | Misc. steam lines<br>throughout      |
| 05               | Middle of N-W room in basement                       | (positive stop                                 | Samples 04-06)                       |
| 06               | N side of N-E room in basement                       | 9  | 5                                    |
| 07               | Men's rest room S of shop                            | Tan 12"x12" Floor<br>Tile/Mastic               | Men's RR's S of<br>shop              |
| 08               | Middle of N-W room in basement                       | 2'x4' Ceiling Tile<br>(fissures)               | Misc. rooms W side<br>of basement    |
| 09               | W end of hall W side of basement                     | Tan 12"x12" Floor<br>Tile/Mastic               | Hall W side of<br>basement           |
| 10               | Middle of hall W side of basement                    | 2'x4' Ceiling Tile<br>(small holes)            | Misc. rooms                          |
| 11               | N side of middle S-W room in<br>basement             | 2'x2' Ceiling Tile<br>(small holes)            | Misc. rooms                          |
| 12               | N side of middle N-W room in<br>basement             | 2'x2' Ceiling Tile<br>(recessed - rough)       | Misc. rooms                          |
| 13               | N side of middle N-W room in<br>basement             | 2'x4' Ceiling Tile<br>(recessed – sq. pattern) | Misc. rooms                          |
| 14               | E wall of middle N-W room in<br>basement             | Drywall  | Misc. walls/ceilings<br>throughout   |
| 15               | S side of middle S-W room in<br>basement             | Ceiling Texturing<br>(sprayed on)              | S side of 2 S-W<br>rooms in basement |
| 16               | S side of middle S-W room in<br>basement             |  | Samples 15-17)                       |
| 17               | S side of middle S-W room W of stairs<br>in basement | 2  | 2                                    |
| 18               | N side of S-W stairs in basement                     | 2'x2' Ceiling Tile<br>(small square pattern)   | Misc. rooms                          |

Date: 2 - 2/-24 Time: \_\_\_\_\_ Relinquished By: \_\_\_\_\_\_ Date: 2/22/24 Time: 10:45 a.m. Received By: EDI2

24 Hour TAT

Building: \_\_\_\_\_ NDOT - 1600 Building \_\_\_\_\_ Date: \_\_02/19/24 \_\_\_\_\_

24010709

#### 1600ULK SAMPLING RECORD

Location:\_\_\_\_\_Lincoln, Nebraska

Inspector: Ron Thompson Job #: 2024-0059 Cert #: NE-MP784

| b #: | 2024-0059 |  |
|------|-----------|--|

| Sample<br>Number | Location  | Material Sampled                       |         | Homog. Area                             |
|------------------|---|--|---------|---|
| 19               | N side of S-W stairs in basement                                    | Rough I<br>(sub-si                     |         | Misc. ceilings that<br>have been abated |
| 20               | N side of men's rest room in basement                               |  |         | RR's middle of<br>basement              |
| 21               | Middle of men's rest room in basement                               | 2'x2' Cei<br>(small                    | -       | RR's middle of<br>basement              |
| 22               | 90° Fitting middle of basement S-W of<br>elevator                   | Hard Packed<br>Insula                  |         | Misc. drain lines                       |
| 23               | Wall in hall W of elevator  | Dryv                                   | vall    | Misc. walls/ceilings<br>throughout      |
| 24               | E end of tank   | Tank ins                               | ulation | Horizontal tank S side of mech. room    |
| 25               | Middle of tank  | (positive stop                         |         | Samples 24-26)                          |
| 26               | W end of tank   | 5                                      |         | 0                                       |
| 27               | 45° Fitting 7' high W of tank<br>4" line – mech. room               | Hard Packed Pipe Fitting<br>Insulation |         | Misc. water lines                       |
| 28               | N-E side of store room B-6  | Off white sheet flooring               |         | Store room B-6                          |
| 29               | Middle of store Room B-4  | 2'x4' Ceiling Tile                     |         | Misc. rooms                             |
| 30               | E end of hall E side of basement                                    | Off White Sheet Flooring               |         | E end of hall E side<br>of basement     |
| 31               | S-E side of B-10  | 2'x2' Ceiling Tile<br>(small holes)    |         | Misc. rooms                             |
| 32               | N side of B-10  | Tan 12"x12" Floor<br>Tile/Mastic       |         | Room B-10                               |
| 33               | 45° Fitting in store room beneath S-E<br>stairs in basement 2"      | Hard Packed Pipe Fitting<br>Insulation |         | Misc. steam lines                       |
| 34               | Wall in engineers' office Middle E side<br>of 1 <sup>st</sup> floor | Plaster                                |         | Misc. walls and<br>ceilings throughout  |
| 35               | N wall in main hall on 1 <sup>st</sup> E of elevator                |  |         |   |
| 36               | Ceiling – middle N-W side of 1 <sup>st</sup> floor                  | 0                                      |         | 2                                       |

| Date: _ | 2-21-24 | Time: | Relinquished By:       | Man | Manymon |
|---------|---------|-------|------------------------|-----|---------|
| Date:   | 2/22/24 | Time: | 10:45 cm, Received By: | -m- |         |

1

## 24 Hour TAT

24010709

Building: \_\_\_\_\_ NDOT - 1600 Building \_\_\_\_\_ Date: \_\_\_02/19/24 \_\_\_\_\_

# 1600ULK SAMPLING RECORD 24010709

Building: \_\_\_\_\_ Date: \_\_\_\_\_ Date: \_\_\_\_\_\_

Location:\_\_\_\_\_\_Lincoln, Nebraska\_\_\_\_\_

Inspector: Ron Thompson Job #: 2024-0059 Cert #: NE-MP784

| Sample<br>Number | Location   | Material Sampled                          | Homog. Area                           |  |
|------------------|--|---|---------------------------------------|--|
| 37               | N wall in W room on 1 <sup>st</sup> floor                            | Plaster                                   | Misc. walls and<br>ceilings throughou |  |
| 38               | Column middle W side of W room on<br>2 <sup>nd</sup> floor           | 1   |                                       |  |
| 39               | Ceiling – Room E of S-E stairs on<br>2 <sup>nd</sup> floor           |   |                                       |  |
| 40               | Wall in store room in men's rest room<br>on 2 <sup>nd</sup> floor    | 2   | 2                                     |  |
| 41               | S side of W room on 1 <sup>st</sup> floor                            | 2'x2' Ceiling Tile<br>(rough)             | Misc. rooms<br>1 <sup>st</sup> floor  |  |
| 42               | Middle S side of 1 <sup>st</sup> floor                               | 1   |                                       |  |
| 43               | S side of S-E room on 1 <sup>st</sup> floor                          | 2   | 2                                     |  |
| 44               | S side of N-E room on 1 <sup>st</sup> floor                          | Rough Plaster<br>(sub-strate)             | Misc. ceilings that<br>were abated    |  |
| 45               | E end of hall on 1 <sup>st</sup>                                     |   |                                       |  |
| 46               | N side of W room on 1 <sup>st</sup>                                  |   |                                       |  |
| 47               | S-W side of W room on 2 <sup>nd</sup> floor                          |   |                                       |  |
| 48               | Room W of women's RR on 2 <sup>nd</sup> floor                        | 2   | 2                                     |  |
| 49               | E side of N-E room on 1 <sup>st</sup> floor above<br>plaster ceiling | Black Wrap on pipe fittings               | Misc. fittings<br>throughout          |  |
| 50               | N side of closet middle E room on 1 <sup>st</sup><br>floor           | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 1 <sup>st</sup><br>floor  |  |
| 51               | W side of middle S-E room on 1st floor                               | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 1 <sup>st</sup><br>floor  |  |
| 52               | Above window in Room E of S-E stairs<br>on 1 <sup>st</sup> floor     | Sprayed on acoustical<br>ceiling material | Above DW that i<br>above windows 1    |  |
| 53               | Steam riser N-E side of men's RR on<br>1 <sup>st</sup> floor         | Mag Pipe Insulation                       | Misc. steam line                      |  |
| 54               | S side of pipe chase between RRs on<br>1 <sup>st</sup> floor         | Hard Packed Pipe Fitting<br>Insulation    | Misc. water line                      |  |

Date: <u>2/22/24</u> Time: <u>105456.m</u> Received By: <u>EDP</u>\_\_\_\_\_

## 24 Hour TAT

#### 1600ULK SAMPLING RECORD

Building: \_\_\_\_\_ NDOT - 1600 Building \_\_\_\_\_ Date: \_\_02/19/24 \_\_\_\_\_

24010709

Location: Lincoln, Nebraska

Inspector: <u>Ron Thompson</u> Job #: <u>2024-0059</u> Cert #: <u>NE-MP784</u>

| Sample<br>Number | Location  | Material Sampled                          | Homog. Area   |  |
|------------------|---|---|---|--|
| 55               | Room W of women's RR on 2 <sup>nd</sup> floor                     | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 1 <sup>st</sup><br>floor                  |  |
| 56               | By water fountain middle of hall<br>On 1 <sup>st</sup> floor      | Off White 9"x9" Floor<br>Tile/Mastic      | Hall on 1 <sup>st</sup> floor                         |  |
| 57               | By water fountain middle of hall<br>On 1 <sup>st</sup> floor      | Tar Paper                                 | Hall on 1 <sup>st</sup> floor<br>(beneath floor tile) |  |
| 58               | S side of room E of S-E stairs on<br>1 <sup>st</sup> floor        | Gray 9"x9" Floor Tile/Mastic              | Misc. rooms 1 <sup>st</sup><br>_floor                 |  |
| 59               | S-W room in N wing on 1 <sup>st</sup> floor                       | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 1 <sup>st</sup><br>floor                  |  |
| 60               | S side of room W of mother's room on 1 <sup>st</sup> floor        | 2'x2' Ceiling Tile<br>(recessed – smooth) | Misc. rooms   |  |
| 61               | Middle of hall on 2 <sup>nd</sup> floor                           | 2'x2' Ceiling Tile<br>(recessed – rough)  | Misc. rooms on 2 <sup>nd</sup><br>floor               |  |
| 62               | Middle S side of N wing on 2 <sup>nd</sup> floor                  | 1   |   |  |
| 63               | Middle N side of W room on 2 <sup>nd</sup> floor                  | 2   | 7   |  |
| 64               | N side of S-W stairs on 2 <sup>nd</sup> floor                     | Sprayed on acoustical<br>ceiling material | Misc. ceilings on<br>2 <sup>nd</sup> floor            |  |
| 65               | N-E side of N wing on 2 <sup>nd</sup> floor                       | (positive stop                            | Samples 64-68)  |  |
| 66               | Middle N side of room E of S-E stairs<br>on 2 <sup>nd</sup> floor |   |   |  |
| 67               | Middle S-E room on 2 <sup>nd</sup> floor                          |   |   |  |
| 68               | N-E side of N-E room on 2 <sup>nd</sup> floor                     | 2   | d   |  |
| 69               | E side of room N of S-W stairs on<br>2 <sup>nd</sup> floor        | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 2 <sup>nd</sup><br>floor                  |  |
| 70               | W side of N wing on 2 <sup>nd</sup>                               | Tan 9"x9" Floor Tile/Mastic               | Misc. rooms 2 <sup>nd</sup><br>floor                  |  |
| 71               | S side of room E of S-W stairs on<br>2 <sup>nd</sup> floor        | Gray 9"x9" Floor Tile/Mastic              | Misc. rooms 2 <sup>nd</sup><br>floor                  |  |
| 72               | S side of pipe chase between RRs on 2 <sup>nd</sup> floor         | Hard Packed Pipe Fitting<br>Insulation    | Misc. water lines                                     |  |

## Date: 2-2/-24 Time: \_\_\_\_\_ Relinquished By: Monthemanon Date: 2/22/22 Time: 10:454.m. Received By: EDR

## 24 Hour TAT

|                  | 1600ULK SAMPL  | ING RECORD                            | 24010/09                                |  |  |
|------------------|--|---------------------------------------|---|--|--|
| uilding: _       | 1600ULK SAMPLING RECORD         240/0709           NDOT - 1600 Building         Date: 02/19/24 |                                       |   |  |  |
| ocation:         | Lincoln, Nebraska  | · · · · · · · · · · · · · · · · · · · | <u></u>                                 |  |  |
| nspector:        | Ron Thompson Job #:  | 2024-0059 Cert #:                     | <u>NE-MP784</u>                         |  |  |
| Sample<br>Number | Location   | Material Sampled                      | Homog. Area                             |  |  |
| 73               | By elevator on 2 <sup>nd</sup> floor   | Off White 9"x9" Floor<br>Tile/Mastic  | Hall on 2 <sup>nd</sup> floor           |  |  |
| 74               | Wall N-E side of W room on 2 <sup>nd</sup> floor   | Drywall                               | Misc. ceilings and<br>walls             |  |  |
| 75               | Middle N-E side of 2 <sup>nd</sup> floor   | 2'x4' Ceiling Tile<br>(recessed)      | Misc. rooms on 3 <sup>rd</sup><br>floor |  |  |
| 76               | Middle of E room on 2 <sup>nd</sup> floor  | Gray 9"x9" Floor Tile/Mastic          | Misc. rooms 2 <sup>nd</sup><br>floor    |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
|                  |  |                                       |   |  |  |
| ate: _2-2        | <u>21-21</u> Time: Relinquish  | ed By: <u>Ronall</u>                  | mynon                                   |  |  |
| ate: <u>2/22</u> | rize Time: 0,970. Received i   | ру: <u>Си</u>                         |   |  |  |
|                  | 24 Hou   | I <b>r TAT</b>                        |   |  |  |


## Appendix C



# **The Identification Specialists**

## Analysis Report prepared for Bockmann Inc

Report Date: 2/23/2024 Project Name: NDOT - 1600 Building, Lincoln, Nebraska Project #: 2024-0059





NVLAP LAB CODE 200870-0

10501 Trade Court | North Chesterfield, Virginia 23236 888.895.1177 | 804.897.1177 | fax: 804.897.0070 | IAQ@SanAir.com | SanAir.com



Name: Bockmann Inc Address: 1600 Center Park Road Lincoln, NE 68512-1228 Phone: 402-423-6631 x 104 SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Dear Ron Thompson,

We at SanAir would like to thank you for the work you recently submitted. The 76 sample(s) were received on Thursday, February 22, 2024 via UPS. The final report(s) is enclosed for the following sample(s): 01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

andra Sobiint

Sandra Sobrino Asbestos & Materials Laboratory Manager SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

Sample conditions:

- 76 samples in Good condition.



Name: Bockmann Inc Address: 1600 Center Park Road Lincoln, NE 68512-1228 **Phone:** 402-423-6631 x 104

SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|   | Stereoscopic                            | Components                 |               |                              |
|---|---|----------------------------|---------------|------------------------------|
| SanAir ID / Description   | Appearance                              | % Fibrous                  | % Non-fibrous | Asbestos Fibers              |
| 01 / 24010709-001<br>Hard Packed Pipe Fitting<br>Insulation S-E Side Of Shop 45                 | Gray<br>Non-Fibrous<br>Heterogeneous    |                            | 90% Other     | 10% Chrysotile               |
| 02 / 24010709-002<br>Hard Packed Pipe Fitting<br>Insulation N-E Side Of N-W Room<br>In          |   |                            |               | Not Analyzed                 |
| 03 / 24010709-003<br>Hard Packed Pipe Fitting<br>Insulation Middle N-W Side Of                  |   |                            |               | Not Analyzed                 |
| 04 / 24010709-004<br>Mag Pipe Insulation Hall W Of<br>Mechanical Room In Basement               | Off-White<br>Non-Fibrous<br>Homogeneous |                            | 100% Other    | None Detected                |
| 05 / 24010709-005<br>Mag Pipe Insulation Middle Of N-<br>W Room In Basement Misc.               | White<br>Non-Fibrous<br>Heterogeneous   |                            | 87% Other     | 3% Chrysotile<br>10% Amosite |
| 06 / 24010709-006<br>Mag Pipe Insulation N Side Of N-E<br>Room In Basement Misc.                |   |                            |               | Not Analyzed                 |
| 07 / 24010709-007<br>12"x12" Floor Tile/Mastic Men's<br>Rest Room S Of Shop Men's RR,<br>Tile   | Tan<br>Non-Fibrous<br>Homogeneous       |                            | 100% Other    | None Detected                |
| 07 / 24010709-007<br>12"x12" Floor Tile/Mastic Men's<br>Rest Room S Of Shop Men's RR,<br>Mastic | Yellow<br>Non-Fibrous<br>Homogeneous    |                            | 100% Other    | None Detected                |
| 08 / 24010709-008<br>2'x4' Ceiling Tile (Fissures) Middle<br>Of N-W Room In Basement            | Gray<br>Fibrous<br>Homogeneous          | 45% Cellulose<br>45% Glass | 10% Other     | None Detected                |
| 09 / 24010709-009<br>12"x12" Floor Tile/Mastic W End<br>Of Hall W Side Of Basement, Tile        | Tan<br>Non-Fibrous<br>Homogeneous       |                            | 100% Other    | None Detected                |

Analyst:

2/23/2024 Analysis Date:

Approved Signatory:

13/auto

2/23/2024 Date:

Page 3 of 19



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|   | Stereoscopic                         | Components                 |               |                 |
|---|--------------------------------------|----------------------------|---------------|-----------------|
| SanAir ID / Description   | Appearance                           | % Fibrous                  | % Non-fibrous | Asbestos Fibers |
| 09 / 24010709-009<br>12"x12" Floor Tile/Mastic W End<br>Of Hall W Side Of Basement,<br>Mastic | Yellow<br>Non-Fibrous<br>Homogeneous |                            | 100% Other    | None Detected   |
| 10 / 24010709-010<br>2'x4' Ceiling Tile (Small Holes)<br>Middle Of Hall W Side Of             | White<br>Fibrous<br>Homogeneous      | 60% Cellulose<br>20% Glass | 20% Other     | None Detected   |
| 11 / 24010709-011<br>2'x2' Ceiling Tile (Small Holes) N<br>Side Of Middle S-W Room            | White<br>Fibrous<br>Homogeneous      | 60% Cellulose<br>20% Glass | 20% Other     | None Detected   |
| 12 / 24010709-012<br>2'x2' Ceiling Tile (Recessed-<br>Rough) N Side Of Middle N-W             | White<br>Fibrous<br>Homogeneous      | 75% Glass<br>15% Cellulose | 10% Other     | None Detected   |
| 13 / 24010709-013<br>2'x4' Ceiling Tile (Recessed-Sq.<br>Pattern) N Side Of Middle N          | White<br>Fibrous<br>Homogeneous      | 60% Cellulose<br>20% Glass | 20% Other     | None Detected   |
| 14 / 24010709-014<br>Drywall E Wall Of Middle N-W<br>Room In Basement Misc. Walls/            | White<br>Non-Fibrous<br>Homogeneous  | 5% Cellulose               | 95% Other     | None Detected   |
| 15 / 24010709-015<br>Ceiling Texturing (Sprayed On) S<br>Side Of Middle S-W Room In           | White<br>Non-Fibrous<br>Homogeneous  |                            | 100% Other    | None Detected   |
| 16 / 24010709-016<br>Ceiling Texturing (Sprayed On) S<br>Side Of Middle S-W Room In           | White<br>Non-Fibrous<br>Homogeneous  |                            | 100% Other    | None Detected   |
| 17 / 24010709-017<br>Ceiling Texturing (Sprayed On) S<br>Side Of Middle S-W Room W            | White<br>Non-Fibrous<br>Homogeneous  |                            | 100% Other    | None Detected   |
| 18 / 24010709-018<br>2'x2' Ceiling Tile (Small Square<br>Pattern) N Side Of S-W               | White<br>Fibrous<br>Homogeneous      | 60% Cellulose<br>20% Glass | 20% Other     | None Detected   |
| Analyst:  | galifier                             | Approved                   | Signatory:    | ttt             |

Analysis Date:

2/23/2024

(-)

2/23/2024 Date:



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|  | Stereoscopic                          | Components                 |               |                              |
|--|---------------------------------------|----------------------------|---------------|------------------------------|
| SanAir ID / Description  | Appearance                            | % Fibrous                  | % Non-fibrous | Asbestos Fibers              |
| 19 / 24010709-019<br>Rough Plaster (Sub-Strate) N Side<br>Of S-W Stairs In Basement    | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other    | < 1% Chrysotile              |
| 20 / 24010709-020<br>12"x12" Floor Tile/Mastic N Side<br>Of Men's Rest Room In, Tile   | Tan<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other    | None Detected                |
| 20 / 24010709-020<br>12"x12" Floor Tile/Mastic N Side<br>Of Men's Rest Room In, Mastic | Yellow<br>Non-Fibrous<br>Homogeneous  |                            | 100% Other    | None Detected                |
| 21 / 24010709-021<br>2'x2' Ceiling Tile (Small Holes)<br>Middle Of Men's Rest Room     | White<br>Fibrous<br>Homogeneous       | 60% Cellulose<br>20% Glass | 20% Other     | None Detected                |
| 22 / 24010709-022<br>Hard Packed Pipe Fitting<br>Insulation 90 Fitting Middle Of       | White<br>Non-Fibrous<br>Heterogeneous |                            | 85% Other     | 10% Chrysotile<br>5% Amosite |
| 23 / 24010709-023<br>Drywall Wall In Hall W Of Elevator<br>Misc. Walls/Ceilings        | White<br>Non-Fibrous<br>Homogeneous   | 3% Glass                   | 97% Other     | None Detected                |
| 24 / 24010709-024<br>Tank Insulation E End Of Tank<br>Horizontal Tank S Side Of Mech   | White<br>Non-Fibrous<br>Heterogeneous |                            | 85% Other     | 10% Chrysotile<br>5% Amosite |
| 25 / 24010709-025<br>Tank Insulation Middle Of Tank<br>Horizontal Tank S Side Of       |                                       |                            |               | Not Analyzed                 |
| 26 / 24010709-026<br>Tank Insulation W End Of Tank<br>Horizontal Tank S Side Of Mech   |                                       |                            |               | Not Analyzed                 |
| 27 / 24010709-027<br>Hard Packed Pipe Fitting<br>Insulation 45 Fitting 7' High W Of    | Gray<br>Non-Fibrous<br>Heterogeneous  |                            | 90% Other     | 10% Chrysotile               |
|  | Alter                                 | Approved                   | Signatory:    | titta —                      |

Analysis Date:

2/23/2024

([]]

2/23/2024 Date:



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|  | Stereoscopic                              | Components                 |                                 |                                |
|--|---|----------------------------|---------------------------------|--------------------------------|
| SanAir ID / Description  | Appearance                                | % Fibrous                  | % Non-fibrous                   | Asbestos Fibers                |
| 28 / 24010709-028<br>Sheet Flooring N-E Side Of Store<br>Room B-6 Store Room B-6                   | Off-White<br>Non-Fibrous<br>Heterogeneous | 15% Cellulose              | 85% Other                       | None Detected                  |
| 29 / 24010709-029<br>2'x4' Ceiling Tile Middle Of Store<br>Room B-4 Misc. Rooms                    | White<br>Fibrous<br>Homogeneous           | 60% Cellulose<br>20% Glass | 20% Other                       | None Detected                  |
| 30 / 24010709-030<br>Sheet Flooring E End Of Hall E<br>Side Of Basement E End Of                   | Off-White<br>Non-Fibrous<br>Heterogeneous | 15% Cellulose              | 85% Other                       | None Detected                  |
| 31 / 24010709-031<br>2'x2' Ceiling Tile (Small Holes) S-E<br>Side Of B-10 Misc Rooms               | White<br>Fibrous<br>Homogeneous           | 60% Cellulose<br>20% Glass | 20% Other                       | None Detected                  |
| 32 / 24010709-032<br>12"x12" Floor Tile/Mastic N Side<br>Of B-10 Room B-10, Tile                   | Tan<br>Non-Fibrous<br>Homogeneous         |                            | 98% Other                       | 2% Chrysotile                  |
| 32 / 24010709-032<br>12"x12" Floor Tile/Mastic N Side<br>Of B-10 Room B-10, Mastic                 | Various<br>Non-Fibrous<br>Heterogeneous   |                            | 100% Other                      | None Detected                  |
| 33 / 24010709-033<br>Hard Packed Pipe Fitting<br>Insulation 45 Fitting In Store<br>Room            | Tan<br>Non-Fibrous<br>Heterogeneous       |                            | 92% Other                       | 8% Chrysotile                  |
| 34 / 24010709-034<br>Plaster Wall In Engineers' Office<br>Middle E Side Of 1st Floor, Plaster      | White<br>Non-Fibrous<br>Heterogeneous     |                            | 100% Other                      | < 1% Chrysotile                |
| 34 / 24010709-034<br>Plaster Wall In Engineers' Office<br>Middle E Side Of 1st Floor, Skim<br>Coat | White<br>Non-Fibrous<br>Homogeneous       |                            | 100% Other                      | None Detected                  |
| 35 / 24010709-035<br>Plaster N Wall In Main Hall On 1st<br>E Of Elevator Misc. Walls, Plaster      | White<br>Non-Fibrous<br>Heterogeneous     |                            | 100% Other                      | < 1% Chrysotile                |
| Analyst: Analysis Date: 2/23/202   | galitar                                   | Approved                   | Signatory: ASTa<br>Date: 2/23/2 | <del>1/1<b>/</b></del><br>2024 |

2/23/2024 Date:



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

## Asbestos Bulk PLM EPA 600/R-93/116

|  | Stereoscopic                          | Com       |               |                 |
|--|---------------------------------------|-----------|---------------|-----------------|
| SanAir ID / Description  | Appearance                            | % Fibrous | % Non-fibrous | Asbestos Fibers |
| 35 / 24010709-035<br>Plaster N Wall In Main Hall On 1st<br>E Of Elevator Misc. Walls, Skim<br>Coat | White<br>Non-Fibrous<br>Homogeneous   |           | 100% Other    | None Detected   |
| 36 / 24010709-036<br>Plaster Ceiling-Middle N-W Side<br>Of 1st Floor Misc. Walls And,<br>Plaster   | White<br>Non-Fibrous<br>Heterogeneous |           | 100% Other    | < 1% Chrysotile |
| 36 / 24010709-036<br>Plaster Ceiling-Middle N-W Side<br>Of 1st Floor Misc. Walls And, Skim<br>Coat | White<br>Non-Fibrous<br>Homogeneous   |           | 100% Other    | None Detected   |
| 37 / 24010709-037<br>Plaster N Wall In W Room On 1st<br>Floor Misc. Walls And, Plaster             | White<br>Non-Fibrous<br>Heterogeneous |           | 100% Other    | < 1% Chrysotile |
| 37 / 24010709-037<br>Plaster N Wall In W Room On 1st<br>Floor Misc. Walls And, Skim Coat           | White<br>Non-Fibrous<br>Homogeneous   |           | 100% Other    | None Detected   |
| 38 / 24010709-038<br>Plaster Column Middle W Side Of<br>W Room On 2nd Floor Misc.                  | White<br>Non-Fibrous<br>Heterogeneous |           | 100% Other    | < 1% Chrysotile |
| 39 / 24010709-039<br>Plaster Ceiling-Room E Of S-E<br>Stairs On 2nd Floor Misc., Plaster           | White<br>Non-Fibrous<br>Heterogeneous |           | 100% Other    | < 1% Chrysotile |
| 39 / 24010709-039<br>Plaster Ceiling-Room E Of S-E<br>Stairs On 2nd Floor Misc., Skim<br>Coat      | White<br>Non-Fibrous<br>Homogeneous   |           | 100% Other    | None Detected   |
| 40 / 24010709-040<br>Plaster Wall In Store Room In<br>Men's Rest Room On 2nd Floor,<br>Plaster     | White<br>Non-Fibrous<br>Heterogeneous |           | 100% Other    | < 1% Chrysotile |
| Analyst:   | alter                                 | Approved  | d Signatory:  | tita-           |

Analysis Date:

a contraction 2/23/2024

1) auto

2/23/2024 Date:



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|  | Stereoscopic                          | Components                 |                 |                 |
|--|---------------------------------------|----------------------------|-----------------|-----------------|
| SanAir ID / Description  | Appearance                            | % Fibrous                  | % Non-fibrous   | Asbestos Fibers |
| 40 / 24010709-040<br>Plaster Wall In Store Room In<br>Men's Rest Room On 2nd Floor,<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous   |                            | 100% Other      | None Detected   |
| 41 / 24010709-041<br>2'x2' Ceiling Tile (Rough) S Side Of<br>W Room On 1st Floor                 | White<br>Fibrous<br>Heterogeneous     | 75% Glass<br>15% Min. Wool | 10% Other       | None Detected   |
| 42 / 24010709-042<br>2'x2' Ceiling Tile (Rough) Middle S<br>Side Of 1st Floor Misc.              | White<br>Fibrous<br>Heterogeneous     | 75% Glass<br>15% Min. Wool | 10% Other       | None Detected   |
| 43 / 24010709-043<br>2'x2' Ceiling Tile (Rough) S Side Of<br>S-E Room On 1st Floor               | White<br>Fibrous<br>Heterogeneous     | 75% Glass<br>15% Min. Wool | 10% Other       | None Detected   |
| 44 / 24010709-044<br>Rough Plaster (Sub-Strate) S Side<br>Of N-E Room On 1st Floor               | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other      | < 1% Chrysotile |
| 45 / 24010709-045<br>Rough Plaster (Sub-Strate) E End<br>Of Hall On 1st Misc.                    | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other      | < 1% Chrysotile |
| 46 / 24010709-046<br>Rough Plaster (Sub-Strate) N Side<br>Of W Room On 1st Misc.                 | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other      | < 1% Chrysotile |
| 47 / 24010709-047<br>Rough Plaster (Sub-Strate) S-W<br>Side Of W Room On 2nd Floor               | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other      | < 1% Chrysotile |
| 48 / 24010709-048<br>Rough Plaster (Sub-Strate) Room<br>W Of Women's RR On 2nd Floor             | White<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other      | < 1% Chrysotile |
| 49 / 24010709-049<br>Wrap On Pipe Fittings E Side Of<br>N-E Room On 1st Floor Above              | Black<br>Non-Fibrous<br>Heterogeneous | 15% Glass                  | 78% Other       | 7% Chrysotile   |
| Analyst:   | galita                                | Approved                   | Signatory: ASTa | tita            |

Analysis Date:

2/23/2024

1-1

2/23/2024 Date:



SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|   | Stereoscopic                            | copic Components |               |                              |
|---|---|------------------|---------------|------------------------------|
| SanAir ID / Description   | Appearance                              | % Fibrous        | % Non-fibrous | Asbestos Fibers              |
| 50 / 24010709-050<br>9"x9" Floor Tile/Mastic N Side Of<br>Closet Middle E Room On, Tile   | Brown<br>Non-Fibrous<br>Homogeneous     |                  | 97% Other     | 3% Chrysotile                |
| 50 / 24010709-050<br>9"x9" Floor Tile/Mastic N Side Of<br>Closet Middle E Room On, Mastic | Black<br>Non-Fibrous<br>Heterogeneous   |                  | 100% Other    | < 1% Chrysotile              |
| 51 / 24010709-051<br>9"x9" Floor Tile/Mastic W Side Of<br>Middle S-E Room On 1st, Mastic  | Yellow<br>Non-Fibrous<br>Homogeneous    |                  | 100% Other    | None Detected                |
| 51 / 24010709-051<br>9"x9" Floor Tile/Mastic W Side Of<br>Middle S-E Room On 1st, Tile    | Tan<br>Non-Fibrous<br>Homogeneous       |                  | 97% Other     | 3% Chrysotile                |
| 51 / 24010709-051<br>9"x9" Floor Tile/Mastic W Side Of<br>Middle S-E Room On 1st, Mastic  | Black<br>Non-Fibrous<br>Heterogeneous   |                  | 100% Other    | < 1% Chrysotile              |
| 52 / 24010709-052<br>Sprayed On Acoustical Ceiling<br>Material Above Window In Room       | Various<br>Non-Fibrous<br>Heterogeneous |                  | 90% Other     | 10% Chrysotile               |
| 53 / 24010709-053<br>Mag Pipe Insulation Steam Riser<br>N-E Side Of Men's RR On 1st       | White<br>Non-Fibrous<br>Heterogeneous   |                  | 87% Other     | 3% Chrysotile<br>10% Amosite |
| 54 / 24010709-054<br>Hard Packed Pipe Fitting<br>Insulation S Side Of Pipe Chase          | Tan<br>Non-Fibrous<br>Heterogeneous     |                  | 92% Other     | 8% Chrysotile                |
| 55 / 24010709-055<br>9"x9" Floor Tile/Mastic Room W<br>Of Women's RR On 2nd Floor, Tile   | Tan<br>Non-Fibrous<br>Homogeneous       |                  | 97% Other     | 3% Chrysotile                |
| 55 / 24010709-055<br>9"x9" Floor Tile/Mastic Room W<br>Of Women's RR On 2nd Floor,        | Black<br>Non-Fibrous<br>Homogeneous     |                  | 100% Other    | None Detected                |

Analysis Date:

2/23/2024

ſ

1 V

2/23/2024 Date:



SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|   | Stereoscopic                            | Components                 |               |                 |
|---|---|----------------------------|---------------|-----------------|
| SanAir ID / Description   | Appearance                              | % Fibrous                  | % Non-fibrous | Asbestos Fibers |
| 56 / 24010709-056<br>9"x9" Floor Tile/Mastic By Water<br>Fountain Middle Of Hall On, Tile       | Off-White<br>Non-Fibrous<br>Homogeneous |                            | 100% Other    | None Detected   |
| 56 / 24010709-056<br>9"x9" Floor Tile/Mastic By Water<br>Fountain Middle Of Hall On,<br>Mastic  | Various<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other    | None Detected   |
| 57 / 24010709-057<br>Tar Paper By Water Fountain<br>Middle Of Hall On 1st Floor Hall            | Black<br>Fibrous<br>Homogeneous         | 80% Cellulose              | 20% Other     | None Detected   |
| 58 / 24010709-058<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-E Stairs On, Mastic       | Yellow<br>Non-Fibrous<br>Heterogeneous  |                            | 100% Other    | None Detected   |
| 58 / 24010709-058<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-E Stairs On, Tile         | Gray<br>Non-Fibrous<br>Homogeneous      |                            | 97% Other     | 3% Chrysotile   |
| 58 / 24010709-058<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-E Stairs On, Mastic       | Black<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other    | None Detected   |
| 59 / 24010709-059<br>9"x9" Floor Tile/Mastic S-W Room<br>In N Wing On 1st Floor Misc,<br>Mastic | Yellow<br>Non-Fibrous<br>Heterogeneous  |                            | 100% Other    | None Detected   |
| 59 / 24010709-059<br>9"x9" Floor Tile/Mastic S-W Room<br>In N Wing On 1st Floor Misc, Tile      | Tan<br>Non-Fibrous<br>Homogeneous       |                            | 97% Other     | 3% Chrysotile   |
| 59 / 24010709-059<br>9"x9" Floor Tile/Mastic S-W Room<br>In N Wing On 1st Floor Misc,<br>Mastic | Black<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other    | None Detected   |
| 60 / 24010709-060<br>2'x2' Ceiling Tile (Recessed-<br>Smooth) S Side Of Room W Of               | White<br>Fibrous<br>Homogeneous         | 60% Cellulose<br>20% Glass | 20% Other     | None Detected   |

Analysis Date:

2/23/2024

2/23/2024

Date:



SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

#### Asbestos Bulk PLM EPA 600/R-93/116

|   | Stereoscopic                            | Comp                       |                                 |                 |
|---|---|----------------------------|---------------------------------|-----------------|
| SanAir ID / Description   | Appearance                              | % Fibrous                  | % Non-fibrous                   | Asbestos Fibers |
| 61 / 24010709-061<br>2'x2' Ceiling Tile (Recessed-<br>Rough) Middle Of Hall On 2nd        | White<br>Fibrous<br>Homogeneous         | 60% Glass<br>20% Min. Wool | 20% Other                       | None Detected   |
| 62 / 24010709-062<br>2'x2' Ceiling Tile (Recessed-<br>Rough) Middle S Side Of N Wing      | White<br>Fibrous<br>Homogeneous         | 60% Glass<br>20% Min. Wool | 20% Other                       | None Detected   |
| 63 / 24010709-063<br>2'x2' Ceiling Tile (Recessed-<br>Rough) Middle N Side Of W Room      | White<br>Fibrous<br>Homogeneous         | 60% Glass<br>20% Min. Wool | 20% Other                       | None Detected   |
| 64 / 24010709-064<br>Sprayed On Acoustical Ceiling<br>Material N Side Of S-W Stairs       | Various<br>Non-Fibrous<br>Heterogeneous |                            | 90% Other                       | 10% Chrysotile  |
| 65 / 24010709-065<br>Sprayed On Acoustical Ceiling<br>Material N-E Side Of N Wing On      |   |                            |                                 | Not Analyzed    |
| 66 / 24010709-066<br>Sprayed On Acoustical Ceiling<br>Material Middle N Side Of Room      |   |                            |                                 | Not Analyzed    |
| 67 / 24010709-067<br>Sprayed On Acoustical Ceiling<br>Material Middle S-E Room On         |   |                            |                                 | Not Analyzed    |
| 68 / 24010709-068<br>Sprayed On Acoustical Ceiling<br>Material N-E Side Of N-E Room       |   |                            |                                 | Not Analyzed    |
| 69 / 24010709-069<br>9"x9" Floor Tile/Mastic E Side Of<br>Room N Of S-W Stairs On, Tile   | Tan<br>Non-Fibrous<br>Homogeneous       |                            | 97% Other                       | 3% Chrysotile   |
| 69 / 24010709-069<br>9"x9" Floor Tile/Mastic E Side Of<br>Room N Of S-W Stairs On, Mastic | Black<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other                      | None Detected   |
|   | galitar                                 | Approved                   | Signatory: ASTa<br>Date: 2/23/2 | 2024            |
| Analysis Date: 2/23/202   | .т                                      | Daie. 2/23/                |                                 |                 |



SanAir ID Number 24010709 FINAL REPORT 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska Collected Date: 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

### Asbestos Bulk PLM EPA 600/R-93/116

|  | Stereoscopic                            | Comp                       | oonents        |                 |  |
|--|---|----------------------------|----------------|-----------------|--|
| SanAir ID / Description  | Appearance                              | % Fibrous                  | % Non-fibrous  | Asbestos Fibers |  |
| 70 / 24010709-070<br>9"x9" Floor Tile/Mastic W Side Of<br>N Wing On 2nd Misc. Rooms, Tile      | Tan<br>Non-Fibrous<br>Homogeneous       |                            | 97% Other      | 3% Chrysotile   |  |
| 70 / 24010709-070<br>9"x9" Floor Tile/Mastic W Side Of<br>N Wing On 2nd Misc. Rooms,<br>Mastic | Black<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other     | None Detected   |  |
| 71 / 24010709-071<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-W Stairs On, Mastic      | Yellow<br>Non-Fibrous<br>Heterogeneous  |                            | 100% Other     | None Detected   |  |
| 71 / 24010709-071<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-W Stairs On, Tile        | Gray<br>Non-Fibrous<br>Homogeneous      |                            | 97% Other      | 3% Chrysotile   |  |
| 71 / 24010709-071<br>9"x9" Floor Tile/Mastic S Side Of<br>Room E Of S-W Stairs On, Mastic      | Black<br>Non-Fibrous<br>Homogeneous     |                            | 100% Other     | None Detected   |  |
| 72 / 24010709-072<br>Hard Packed Pipe Fitting<br>Insulation S Side Of Pipe Chase               | Tan<br>Non-Fibrous<br>Heterogeneous     |                            | 92% Other      | 8% Chrysotile   |  |
| 73 / 24010709-073<br>9"x9" Floor Tile/Mastic By Elevator<br>On 2nd Floor Hall On 2nd, Tile     | Off-White<br>Non-Fibrous<br>Homogeneous |                            | 100% Other     | None Detected   |  |
| 73 / 24010709-073<br>9"x9" Floor Tile/Mastic By Elevator<br>On 2nd Floor Hall On 2nd, Mastic   | Various<br>Non-Fibrous<br>Heterogeneous |                            | 100% Other     | None Detected   |  |
| 74 / 24010709-074<br>Drywall Wall N-E Side Of W Room<br>On 2nd Floor Misc. Ceilings            | White<br>Non-Fibrous<br>Homogeneous     | 5% Cellulose               | 95% Other      | None Detected   |  |
| 75 / 24010709-075<br>2'x4' Ceiling Tile (Recessed)<br>Middle N-E Side Of 2nd Floor             | White<br>Fibrous<br>Homogeneous         | 60% Glass<br>20% Min. Wool | 20% Other      | None Detected   |  |
| Analyst:   | galifin                                 | Approved                   | Signatory: AST | tt the          |  |

Analysis Date:

2/23/2024

// V

2/23/2024 Date:



SanAir ID Number 24010709 **FINAL REPORT** 2/23/2024 12:09:55 PM

Project Number: 2024-0059 P.O. Number: Project Name: NDOT - 1600 Building, Lincoln, Nebraska **Collected Date:** 2/19/2024 Received Date: 2/22/2024 10:45:00 AM

Analyst: Magalis, Lane

## Asbestos Bulk PLM EPA 600/R-93/116

|  | Components   |  |   |  |
|--|--|--|---|--|
| Appearance                             | % Fibrous  | % Non-fibrous  | Asbestos Fibers   |  |
| Yellow<br>Non-Fibrous<br>Heterogeneous |  | 100% Other   | None Detected   |  |
| Gray<br>Non-Fibrous<br>Homogeneous     |  | 97% Other  | 3% Chrysotile   |  |
| Black<br>Non-Fibrous<br>Homogeneous    |  | 100% Other   | None Detected   |  |
|  | Yellow<br>Non-Fibrous<br>Heterogeneous<br>Gray<br>Non-Fibrous<br>Homogeneous<br>Black<br>Non-Fibrous | Yellow<br>Non-Fibrous<br>Heterogeneous<br>Gray<br>Non-Fibrous<br>Homogeneous<br>Black<br>Non-Fibrous | Yellow<br>Non-Fibrous<br>Heterogeneous100% OtherGray<br>Non-Fibrous<br>Homogeneous97% OtherBlack<br>Non-Fibrous100% Other |  |

Analyst:

Lelagaliti

Analysis Date:

2/23/2024

Approved Signatory:

Stattle

2/23/2024 Date:

#### **Disclaimer**

This report is the sole property of the client named on the SanAir Technologies Laboratory chainof-custody (COC). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced except in full without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof, which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means. The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition in which they arrived at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, po number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted. This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC. AIHA LAP, LLC or any other U.S. governmental agencies and may not be accredited by every local, state, and federal regulatory agencies. Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

#### NYELAP Disclaimer:

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

#### Asbestos Accreditations

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0 City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460 Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397 California State Environmental Laboratory Accreditation Program Certificate Number 2915 Colorado Department of Public Health and Environment Registration Number AL-23143 Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105 Massachusetts Department of Labor Standards Asbestos Analytical Services License Number: AA000222

State of Maine Department of Environmental Protection License Number: LB-0075, LA-0084 New York State Department of Health Laboratory ID: 11983

State of Rhode Island Department of Health Certification No.: PCM00126, PLM00126, TEM00126 Texas Department of State Health Services License Number: 300440


Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323

State of Washington Department of Ecology Laboratory ID: C989

State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616 Vermont Department of Health License Number: Asb-Co-An-000006

Louisiana Department of Environmental Quality AI Number 212253, Certificate #05088

# Appendix D



License #: 784 Status: Active Expiration: 03/05/2025

Midwest **Training Institute** 

A Higher Standard of Training

An ATC Company

This is to certifies that

Ron Shompson

has completed the requisite training for asbestos accreditation under TSCA Title II, 15 U.S.C. 2646 and the State of Nebraska Asbestos Regulations and passed the associated examination with a score of 70% or better.

EPA AHERA/Nebraska Asbestos Inspector/Management Planner Refresher Course

Midwest Training Institute, Inc. 11117 Mockingbird Drive Omaha, NE 68137 (402) 505-2940 (402) 515-0585 www.midwesttrainingsite.com

Course Location: Omaha, NE

Instructor

Course Date: 06/29/2023 Examination Date: 06/29/2023 Expiration Date: 06/29/2024 Certificate # MTIPJ 0209 IMPR Course Length- 8 Hours