

Typical X-Section (Pink)

3850-2-E-22 – Joint Pavement Repair

Revision 22

March 2017: Plan 3850-2-e-21 changed to 3850-2-e-22 effective March 2017 Letting.

Took Transverse Joint Detail off sheet 1 & 6. Added it to sheet 5, 8, 9 & 10. Changed the 3/16" saw joint cut to 1/4" on all Transverse Joint Details.

3851-2-E-15 – Joint Pavement Repair (Overlay)

Revision 22

Took the Transverse Joints detail off of sheet 1 & 6. Added it to sheet 4, 5, 7 & 9. Changed the 3/16" saw joint cut to 1/4" on all Transverse Joint Details.