

Hartington (0B4)

Elevation 1387'

AWOS/ASOS	Minneapolis Center	CTAF
None	124.1	122.9 L



Rwy 31 Ldg 3550'

Runway	Surface	Traffic Pattern	Runway Lights
13 / 31	Concrete	1000-LH / 1000-LH	MIRL
03 / 21	Turf	1000-LH / 1000-LH	None
Airport Manager	Tom Becker		402-254-7317
FBO	Becker Flying Service, Inc.		402-254-7317
Fuel	100 LL Call 402-254-6916/3812	Hours	Attended Continuously

Hartington Municipal Airport /
Bud Becker Field

N 42°36.21' W 97°15.16'