

Tier	Control Number	Project Number	Project Location	Roadway Summary	Bridge Work Summary	Design Manager	Fiscal Year	Estimate	Rdwy	Bridge	Enviro. Services	Survey	ROW	Public Inv.	Planning
------	----------------	----------------	------------------	-----------------	---------------------	----------------	-------------	----------	------	--------	------------------	--------	-----	-------------	----------

**Group 1**

1	32312	STP-D3(107)	Norfolk NE Bridges (CHBP)	Approach work necessary for Replacements	7- Bridge size structures, 7- Bridge replacements	Baird	2021	\$11.34M	Yes	Yes	Yes	By NDOT	By NDOT	Yes	No
2	32290	STP-32-6(115)	N-57 East	Resurf., G.R., 14.99 mi.	5 Bridge size structures: 1 bridge repair, 2 UIP, 2 CBC's	Baird	2023	\$5.34M	Yes	Yes	Yes	Yes	By NDOT	Yes	No

**Group 2**

1	13330	STP-S66E(104)	Burr Spur	Mill and resurf, earth shldr rest., CBC repairs, replace G.R., 6.18 Mi.	1 Bridge size structure: 1 CBC repair	Pillard	2022	\$2.56M	Yes	Yes	Yes	By NDOT	By NDOT	Yes	No
1	32286	STP-15-3(119)	N-91 South	2" inlay-Urban, 4"/4" Rural, Grading, GR, 15.31 mi.	8 Bridge size structures: 6 bridge repairs, 2 CBC's	Baird	2022	\$6.84M	Yes	Yes	Yes	By On Call	By NDOT	Yes	No
3	71224	NH-6-3(131)	Holdrege - Funk	Resurface, RR, LED Lighting & G.R., No ADA, 7.13 Mi.	No Bridge size structures	Pillard	2023	3.11M	Yes	No	Yes	By NDOT	By NDOT	Yes	No

**Group 3**

1	42817	STP-14-1(123)	Superior North and South	Mill/Fill, 6.54 mi.	5 Bridge size structures: 4 bridge repairs, 1 bridge UIP, 1 CBC	Kessler	2022	\$4.04M	Yes	Yes	Yes	By NDOT	By NDOT	Yes	No
1	13398	NH-136-7(127)	Tecumseh East	Mill 2"/Fill 4", trench widening, shldrs mill 1"/Fill 3", taper to 2", earth shldr const., 10.77 mi.	2 Bridge size structures: 1 Bridge repair, 1 CBC	Pillard	2022	\$4.64M	Yes	Yes	Yes	By NDOT	No ROW Need	Yes	No
3	13275	STP-50-1(114)	W. Jct. N-4 - Tecumseh	Concrete Repair w/ 4" overlay, Culv. Ext's, C&F, Shldr Const, G.R., MB Turnouts, Cont. access., 12.03 mi.	5 Bridge size structures: 5 bridge repairs	Pillard	2023	\$9.21M	Yes	Yes	Yes	By NDOT	No ROW Need	Yes	No
3	42766	STP-S40D(107)	Prosser Spur	Mill/Fill, 4.96 mi.	4 Bridge size structures: 2 bridge repairs, 1 bridge UIP, 1 CBC	Kessler	2023	\$2.48M	Yes	Yes	Yes	By NDOT	By NDOT	Yes	No

Tier	Control Number	Project Number	Project Location	Roadway Summary	Bridge Work Summary	Design Manager	Fiscal Year	Estimate	Rdwy	Bridge	Enviro. Services	Survey	ROW	Public Inv.	Planning
------	----------------	----------------	------------------	-----------------	---------------------	----------------	-------------	----------	------	--------	------------------	--------	-----	-------------	----------

**Group 4**

1	42827	STP281-1(110)	Ayr North and South	Resurf., 14.11 mi.	1 Bridge size structure: 1 bridge repair	Kessler	2022	\$9.15M	Yes	Yes	Yes	By NDOT	Yes	Yes	No
3	51462A	STP-30-1(139)	Chappell East	Widen to 28' Top, Trench widen, Lighting, 10.18mi.	5 Bridge size structures: 5 CBC's	Montgomery	2023	\$7.6M	Yes	Yes	Yes	By NDOT	Yes	Yes	No
3	51463A	STP-30-1(140)	US-138 West	Widen to 28' Top, Trench widen, 10.38mi.	3 Bridge size structures: 1 bridge repair, 2 CBC's	Montgomery	2023	\$7.95M	Yes	Yes	Yes	By NDOT	Yes	Yes	No

**Group 5**

1	22752	STP-79-3(108)	North Bend - US-30	Mill 3"/Fill 3", 9" conc. Pvmnt, 2.12 mi.	4 Bridge size structures: 2 bridge repairs, 2 CBC's	Montgomery	2022	\$4.10M	Yes	Yes	Yes	By NDOT	Yes	Yes	No
3	31987	STP-56-5(108)	Cedar Rapids West	RESURF 3"/3", 8.08 mi.	1 Bridge size structure: 1 bridge repair	Baird	2023	\$3.54M	Yes	Yes	Yes	Yes	No ROW Need	Yes	No
3	51561	STP-88-1(110)	S Jct N-71 - Bridgeport	Widen to 28' top, 20.37 mi.	13 Bridge size structures: 9 bridge repairs, 4 CBC's	Montgomery	2023	\$8.0M	Yes	Yes	Yes	By NDOT	Yes	Yes	No

**Group 6**

1	81026	NH-20-4(127)	Stafford-Holt/Antelope Co. Line	Mill/Fill 4", Mill/Fill 2" Shldrs, Then mill 2"/Fill 3", earth shldr Const., 8.07 mi.	5 Bridge size structures: 2 bridge repairs, 3 CBC's	Kessler	2022	\$4.07M	Yes	Yes	Yes	By On Call	Yes	Yes	No
2	61664	NH-80-5(86)	Overton East (Reconst).	7 mi. of I-80 & .38 mi. of L24B	9 Bridge size structures: 4 bridge repairs and widening, 3 bridges UIP, 2 CBC's	Baird	2023	\$38.30M	Yes	Yes	Yes	By NDOT	Yes	Yes	No

Tier	Control Number	Project Number	Project Location	Roadway Summary	Bridge Work Summary	Design Manager	Fiscal Year	Estimate	Rdwy	Bridge	Enviro. Services	Survey	ROW	Public Inv.	Planning
------	----------------	----------------	------------------	-----------------	---------------------	----------------	-------------	----------	------	--------	------------------	--------	-----	-------------	----------

**Group 7**

1	31832	STP-84-5(108)	Bloomfiled to US-81	mill 4", place 4", Conc. Repair, GR, Culvert ext., Curb & Flume, 11.52 mi.	7 Bridge size structures: 1 bridge replacement, 1 bridge repair, 1 CBC repair, 4 CBC's	Baird	2022	\$6.55M	Yes	Yes	Yes	By NDOT	Yes	Yes	No
2	42815	STP-281-1(118)	Red Cloud North and Cowles Spur	Resurf., 9.78mi.	1 Bridge size structure: 1 bridge repair	Kessler	2023	\$4.77M	Yes	Yes	Yes	Yes	Yes	Yes	No
2	42872	STP-14-1(124)	In Clay Center and North	Resurf., 5.06mi., will require Traffic data collection and Public Involvement capabilities	1 Bridge size structure: 1 CBC	Kessler	2023	\$2.44M	Yes	Yes	Yes	Yes	Yes	Yes	No
3	32289	STP-16-3(110)	N. Jct. N-51 - S. Jct N-9	Resurf., 10.64 mi.	7 Bridge size structures: 1 bridge repair, 1 bridge UIP, 5 CBC's	Baird	2023	\$4.58M	Yes	Yes	Yes	Yes	No ROW Need	Yes	No

**Group 8**

1	51268	STP-92-1(117)	Broadwater Southwest	Resurf., Widen 24 to 28' top, grading, G.R., 7.83 mi.	3 Bridge size structures: 1 bridge repair, 1 CBC repair, 1 CBC	Montgomery	2022	\$7.04M	Yes	Yes	Yes	By NDOT	Yes	Yes	No
1	61628	NH-2-3(124)	Anslmo - Merna	Resurf., Parallel to BNSF, ROW for Co. Rd. 429, 12.28 mi.	3 Bridge size structures: 3 CBC's	Baird	2023	\$5.11M	Yes	No	Yes	By NDOT	Yes	Yes	No
3	42819	NH-34-4(134)	In Grand Island and South SB	Resurf., 5.44mi.	7 Bridge size structures: 7 bridge repairs	Kessler	2023	\$2.73M	Yes	Yes	Yes	By NDOT	Yes	Yes	No

Note: Tier indicates the Scope and Contracting priority, Tier 1 would be highest schedule priority.

Yes indicates that services would be contracted to Consultant