RFQ-24xx Multi-Service Project List

| ID | CN | Project Number | Project Name | Roadway Summary * SUE Level C & D anticipated for all projects. Levels A & B are not anticipated. | Bridge Summary *CBCs noted as UIP may require extension | FY | Letting Date* | Estimate (Millions) | Design Manager | Planning | Survey | Env | RDD | Bridge | Bridge H&H | ROW Survey | ROW Design | Public Inv. |
|----|-------|--------------------|----------------------------------|--|--|----|------------------|------------------------|-------------------|----------|--------|-----|-----|--------|------------|------------|------------|-------------|
| 1 | 13306 | STP-8-7(116) | Salem & Falls City Bridges | Approach work necessary for bridge replacements, guardrail. | 3 bridge size structures: 2 replacements with grade raise and 1 UIP. Floodplain certifications are needed for bridge work. | 27 | 8/27/2026** | \$8.65 | Lutz | N | N | Υ | Υ | N | Y | N | N | Y |
| 2 | 13476 | NH-135-6(131) | In Fairbury | Replace concrete pavement with integral curb, remove median, construct two lanes with center turn lane, storm sewer, ADA curb ramps. | No bridge-size structures. | 27 | 12/17/2026 | \$6.75 | Lutz | N | N | Y | Y | N | N | N | N | Y |
| 3 | 13505 | STP-HSIP-79-2(115) | US-34 - Raymond Road | N-79: Mill and resurface roadway and shoulders, culverts, guardrail. S-55J & S-55M: Trench widen, mill and resurface roadway, grading, culverts. | 5 bridge size structures: 1 replacement with grade raise, 1 repair and 3 UIP. Floodplain certifications will be completed by NDOT. | 27 | 8/27/2026 | \$5.50 | Lutz | N | N | Y | Y | N | N | N | N | Y |
| 4 | 13508 | STP-8-6(118) | N-103 - US-77 | Trench widen, mill and resurface roadway, guardrail. | 4 bridge size structures: 2 repairs and 2 UIP. Floodplain certifications are needed for bridge work. | 27 | 8/27/2026 | \$9.90 | Lutz | N | N | Y | Υ | Υ | N | N | N | Y |
| 5 | 22860 | NH-MTIS-680-9(53) | Fort St Blair High Rd., Omaha | Pavement replacement and widening, ramp modifications, grading, guardrail, culverts, lighting, signals, utilities, lighting, noise study, sign replacement. An Interchange Modification Report will be needed. Probable class of NEPA action has not been established. | 5 bridge size structures: 3 repairs and 2 replacements. | 29 | 8/17/2028 | \$51.00 | Wehling | N | N | Υ | Υ | Υ | N | Υ | N | Y |
| 6 | 22871 | NH-MTIS-80-9(205) | N-370 to N-50 | Interchange reconstruction, pavement replacement, grading, culverts, curb and flume, noise study, lighting, sign replacements, local road realignment. An Interchange Modification Report will be needed. | 2 bridge size structures: 2 repairs. Floodplain certifications are needed for bridge work. | 28 | 8/5/2027 | \$16.00 | Wehling | N | N | Y | Y | Y | Ν | N | N | Υ |
| 7 | 42955 | STP-30-4(165) | In Kearney West of UNK | Pavement replacement, lighting, culverts, grading. Additional stakeholder/public outreach anticipated. | 1 bridge size structure: 1 UIP. Floodplain certification is needed for bridge work. | 27 | 8/27/2026** | \$9.70 | Ataullah | N | N | Y | Y | N | N | N | N | Y |

RFQ-24xx Multi-Service Project List

| ID | CN | Project Number | Project Name | Roadway Summary * SUE Level C & D anticipated for all projects. Levels A & B are not anticipated. | Bridge Summary *CBCs noted as UIP may require extension | FY | Letting Date* | Estimate (Millions) | Design Manager | Planning | Survey | Env | RDD | Bridge | Bridge H&H | ROW Survey | ROW Design | Public Inv. |
|----|-------|----------------|--------------------|---|--|----|------------------|------------------------|-------------------|----------|--------|-----|-----|--------|------------|------------|------------|-------------|
| 8 | 42994 | HSIP-81-1(129) | Hebron East | Intersection reconstruction at four locations. Grading, median drains, possible lighting modifications. | 4 bridge size structures: 4 UIP. | 27 | 8/27/2026 | \$4.60 | Ataullah | N | N | Υ | Y | Z | Ν | N | Z | Y |
| 9 | 51671 | STP-30-1(141) | Sidney - Lodgepole | US-30, L-17E and L-17F: Mill and resurface roadway, shoulder widening (US-30), grading, culverts, ADA, other improvements in Village of Lodgepole requiring an agreement. Two interchanges with ramp resurfacing. | 8 bridge size structures: 2 replacements and 6 UIP. Floodplain certifications are needed for bridge work. | 27 | 8/27/2026** | \$10.70 | Wehling | N | N | Υ | Y | N | Υ | N | N | Y |
| 10 | 71248 | STP-136-3(112) | US-6/34-Oxford | Mill and resurface roadway and shoulders where present, grading, culverts, guardrail, possible ADA work. | 5 bridge size structures: 3 repairs and 2 UIP. Floodplain certifications are needed for bridge work. | 28 | 8/5/2027** | \$6.00 | Lutz | N | N | Υ | Y | Υ | N | N | N | Y |
| 11 | 81074 | STP-97-4(114) | Merritt Dam North | Trench widen, mill and resurface roadway, grading, culverts, guardrail. | bridge size structure: bridge repair. Floodplain certification is required (no floodplain permit needed). | 28 | 8/5/2027** | \$10.70 | Ataullah | N | Y | Y | Υ | Υ | N | Υ | N | N |

^{*} All project letting dates are subject to change. PS&E dates typically occur 4 months in advance of the scheduled letting.

^{**} Project is unapproved at the time of publication. Schedule will be evaluated at time of approval.